




Assembly Drawing

Parts List

Part #	Description	QTY.
1	Screw	3
2	Motor Cover	1
3	Power Cord	1
4	Top Housing	1
5	Switch Plate	1
6	Lock Stop	1
7	Grinding Wheel Base	1
8	Grinding Wheel	1
9	Grinder Lock Cap	1
10	Screw	2
11	Grinding Wheel Cover	1
13	Punching Axis	1
14	Torsion Spring	1
15	Switch Circuit Board	1
16	Nut	1
17	Base	1
18	Lock Wheel	1
19*	Screw	1
20*	Washer	1
21*	Bearing	1
22*	Swing Arm	1
23*	Chain Stop	1

Part #	Description	QTY.
24*	Tension Spring	1
25*	Retaining Ring	1
26*	Lower Knob	1
27*	Screw	1
28*	Bolt	1
29*	Chain Saw Frame	1
30*	Square Neck Screw	2
31*	Sliding Guide	2
32*	Pad	2
33*	Screw	1
34*	Handle	1
35*	Spring	1
36*	Lock Screw	1
37	Retaining Ring (10)	2
38	Motor	1
39*	Washer	1
40*	Nut	1
42	Safe guard	1
43	Screw	2
44	Spring washer	2
45	Nut	2
46	Pressure panel	1
47	Screw	2

Assembly Drawing

